



Infrared Window Installation Guide

The Infrared Window is a precision made accessory which, when accurately installed, will give years of trouble free service. Read and understand these instructions thoroughly before attempting to install the units.

All of the items shown in this Installation Guide are available from Hawk I.R. International at 011 44 1642 497000 or <http://www.fluke.com/irwindows>.

M Range for use on a flat surface of a Type 1 enclosure.

C Range for use on a flat surface of a Type 3/12 enclosure.

Warning

Failure to follow these instructions may lead to damage or injury. Comply with local and national safety requirements when working in hazardous locations.

March 2009
© 2009 Fluke Corporation. Product specifications are subject to change without notice. All rights reserved.

Before You Start

The installation may be carried out by using either an electro-hydraulic hole punch (Figure 1, Item 1) or a circular hole saw (Figure 2, Item 1).




Figure 1



Figure 2

Tools Required:

1. Electro-hydraulic punch (Figure 1) or hole saw (Figure 2)
2. Drilling machine
3. Conedrill
4. Pozidrive screwdriver
5. Center Punch
6. 6 mm (1/4") High-speed twist drill
7. Tapping drill:
for 25 mm (1") units use 2.78 mm (7/64")
for 50 mm (2") units use 2.78 mm (7/64")
for 75 mm (3") units use 3.57 mm (9/64")
for 100 mm (4") units use 3.57 mm (9/64")
8. Digital vernier calipers.

 **Safety First**
Wear eye protection.

Getting Started

Step 1: *Unpack and Check*

When your Infrared Window arrives, carefully unpack the unit.

Remove the two front security screws and lay out the components. Check that you have all of the parts.


1. Security screws (2)
2. Security cover (1)
3. 2-hole gasket (1)
4. Fixing screws (various)
5. Drilling template (1)
6. Installation instructions (1)
7. Aluminium frame (1)



Figure 3

Step 2: *Fit the Drilling Template onto a Flat Surface*

Having decided on the correct position for the unit, select the drilling template. Peel off the back and stick to the panel with the wording horizontal (Figure 4).

 **Safety First**
Wear eye protection.




Figure 4

Step 3: Center Punch

Using the center punch, punch the fixing holes as marked and 1 No. center hole (Figure 5).



Figure 5

Step 4: Drill Center Hole

Using the 6 mm (1/4") twist drill, drill out the center hole (B) (Figure 6).

- For 25 mm (1") and 50 mm (2") units, proceed to step 5.
- For 75 mm (3") and 100 mm (4") units, proceed to step 6.




Figure 6

Step 5: Drill Fixing Holes

Using the 2.78 mm (7/64") twist drill, drill out the fixing holes (Figure 7).

- If using hole saws, proceed to step 7(A).
- If using the hole punch, proceed to step 7(B).




Figure 7

Step 6: Drill Fixing Holes

Using the 3.57 mm (9/64") twist drill, drill out the fixing holes (Figure 8).




Figure 8

- If using hole saws, proceed to step 7(A).
- If using the hole punch, proceed to step 7(B).

Step 7(A): Enlarging the Center Hole (Hole Saw)

From the table below, select the correct size of hole saw. Proceed to step 8(A).

Table 1.

Infrared Window Size	Hole Saw Size
25 mm (1")	22 mm (7/8")
50 mm (2")	43 mm (1-3/4")
75 mm (3")	68 mm (2-5/8")
100 mm (4")	93 mm (3-5/8")

Step 8(A): Enlarging the Center Hole (Hole Saw)

Using the 6 mm (1/4") hole as a pilot hole, enlarge the center hole using the selected hole saw (Figure 9). De-burr all of the holes and treat as required. Proceed to step 9.



Figure 9

Step 7(B): Enlarging the Center Hole (Hole Punch)

Refer to the Greenlee L60 manual and follow all safety procedures.

⚠ Safety First

Wear eye protection.

From Table 2, select the correct drawbar/punch/die/kwik stepper combination.

Using the Kwik Stepper, enlarge the 6mm center hole (Figure 10) to the size shown in the Table 2. Proceed to step 8(B).




Figure 10

Table 2.

Infrared Window Size	Punch/Die/Part No.	Size	K/Step
25 mm (1")	500-4006/500-4722	22.5 mm/0.9"	10 mm/0.4"
50 mm (2")	500-6974/500-4013	43.2 mm/1.7"	20 mm/0.8"
75 mm (3")	500-4247/500-4246	69.9 mm/2.75"	20 mm/0.8"
100 mm (4")	500-6333/500-6335	92 mm/3.62"	20 mm/0.8"

Step 8(B): Enlarging the Center Hole (Hole Punch)

Referring to Table 2, and following the instructions in the LS60 Plus Greenlee Instruction Manual, punch out the center hole (Figure 11).

Step 9: De-Burr the Holes, Remove any Shavings and the Self Adhesive Template

Degrease the front panel.

⚠ Safety First

Keep the workplace tidy.

Step 10: Fix Infrared Window

Peel off the protective cover from the rear panel gasket on the Infrared Window's aluminium frame (Figure 12).

Align the fixing holes and firmly press the Infrared Window into place (Figure 13).

Using the correct sized screwdriver and the countersunk screws provided, fix back the Infrared Window (Figure 14).

Gradually advance each fixing until the gasket is seen to compress evenly, in accordance with Table 3.

Step 11 - Fitting Security Cover

Peel off the cover from the 2-hole gasket (Figure 15).

Align the gasket with the two fixing holes positioned vertically and press the gasket into position (Figure 16).

Fit the security cover using the two security screws provided (Figure 17).



Figure 11



Figure 12



Figure 13



Figure 14




Figure 15



Figure 16



Figure 17



Figure 18

The Infrared Window is ready for use - Remember to remove the cover before imaging (Figure 18).

Gasket Compression Table

Tighten taptite screws until gasket compresses as listed in Table 3.

Note

Take all measurements with digital vernier calipers.

Table 3.

2" Compression Table			
Standard Gasket		Premier Gasket	
U/C	C	U/C	C
16.8 mm	16.3 mm	16.3 mm	15.0 mm
0.663"	0.643"	0.643"	0.591"
3" Compression Table			
16.8 mm	16.3 mm	16.3 mm	15.0 mm
0.663"	0.643"	0.643"	0.591"
4" Compression Table			
20.4 mm	19.9 mm	N/A	N/A
0.805"	0.784"	N/A	N/A
U/C = Overall dimension - Exterior of security cover to front face of the panel with gasket uncompressed.			
C = Overall dimension - Exterior of security cover to front face of the panel with gasket compressed.			